



Fast Filling fibers as they drop through (first try = 5min, same as initial Oleg's design)




Easy to check for unfilled
fibers




Fiber drop through an hang
on screens

Scale up to 2x1 bow tie blocks




3D model from Spencer Locks (SBU)



Two module length

Two module width


Help registration from both sides



Two module length

Ideas for scale up to 2x2 tower blocks

3D model from Spencer Locks (SBU)



Two module width

